

DO15 RC Indoor Phase VI Test Daily Notes

Date: June 13, 2019

Time: 9:05 am

Cycle count: 675

Overlay Bottom Temp: T1 North: 26.72°F T1 South: 27.95°F

Ambient Temp: 66.80°F

North Section Observation

- 1 crack through SG1-N-0, approximately 2.5 inches (Fig 1).
- 1 crack through SG6-N-0, approximately 2.5 inches (Fig 2).
- Surface crack approximately from 7 to 56.5 inch. (Fig 3).

South Section Observation

- 1 crack through SG1-S-0, approximately 2.5 inches (Fig 4).
- Surface crack runs through SG3-S-5, SG4-S-5, approximately from 11 to 48.5 inch (Fig 5)

Issues

- No



Fig 1 Bottom-up crack at SG1-N-0 2.5 inch long



Fig 2 Bottom-up crack at SG6-N-0 2.5 inch long




Fig 3 Surface crack on North Section approximately 7 to 56.5 inch



Fig 4 Bottom-up crack at SG1-S-0 2.5 inch long




Fig 5 Surface crack on south section between 11'' and 48.5''

Date: June 12, 2019

Time: 1:00 pm

Cycle count: 695

Overlay Bottom Temp: T1 North: 26.66°F T1 South: 28.13°F

Ambient Temp: 72.46°F

North Section Observation

- No change

South Section Observation

- No change