

DO15 RC Indoor Phase VI Test Daily Notes

Date: July 11, 2019

Time: 8:50 am

Cycle count: 3531

Overlay Bottom Temp: T1 North: 29.37°F T1 South: 31.06°F

Ambient Temp: 77.75°F

North Section Observation

- No change from last observation.
- Bottom up crack at inner vertical edge (Fig 1). Bottom up crack at outer vertical edge (Fig 2).
- Surface crack connected to the bottom-up crack of the outer edge (Fig 3), and the inner vertical edge (Fig 4).

South Section Observation

- No change from last observation.
- Bottom up crack at inner vertical edge (Fig5). Bottom up crack at outer vertical edge (Fig 6).
- Surface crack reached the inner vertical edge (Fig 7), approximately 3 inches from the outer vertical edge, no change (Fig 8)

Issues

- None



Fig 1 Bottom-up crack at north section inner vertical edge reached top surface



Fig 2 Bottom-up crack at north section outer edge reached top surface




Fig 3 Surface crack on North Section reached outer edge



Fig 4 North section surface crack reached inner vertical edge



Fig 5 Bottom-up crack at inner vertical edge of south section reached top surface




Fig 6 Bottom-up crack at SG6-S-0 3 inch long




Fig 7 South section surface crack reached the inner vertical edge



Fig 8 South section surface crack 3 inches from the outer vertical edge




Fig 9 Surface crack on the north section




Fig 10 Surface crack on the south section