

DO15 RC Indoor Phase VI Test Daily Notes

Date: June 11, 2019

Time: 11:50am

Cycle count:

Overlay Bottom Temp: T1 North: 26.05°F T1 South: 27.83°F

Ambient Temp: 75.14°F

North Section Observation

- 1 crack through SG1-N-0, approximately 2.0 inches (Fig 1).
- 1 crack through SG6-N-0, approximately 2.25 inches (Fig 2).
- Surface gage SG3-N-5 and SG4-N-5 located on the top of the HMA overlay failed.

South Section Observation

- 1 crack through SG1-S-0, approximately 0.75 inches (Fig 3).

Issues

- No



Fig 1 Bottom-up crack at SG1-N-0



Fig 2 Bottom-up crack at SG6-N-0



Fig 3 Bottom-up crack at SG1-S-0