


## CC2 Test Strip Sensor Diagrams

Sensor locations

- (1) Sliding Gage (SGs)
- (2) Joint Gages (Js)
- (3) Temperature Gages (Ts)
- (4) Vertical Deflection Gages (CTs and DTs)

**T – Temperature**  
**J – Joint Gages**  
**SG – Sliding gages**  
**CSG – Strain gages**



## CC2 Test Strip Sensor Diagrams

### Strain gages in slabs S6 and S3

Most strain gages were located in Slab S3 (15' by 15' ) and S6 (20' by 20')

