

TO15 RC Outdoor Phase 1 Daily Notes

Date: 02/14/2020

Temperature: 35.8°F (Ambient)

Test starts at 6:40AM, stops at 13:08PM, 620 passes scheduled for today, and total of 2356 passes completed.

Observations:

West side

TT56 joint west side, no further crack propagation observed compared to yesterday.



Figure 1. TT56 Joint

Bottom up crack at TT45 west vertical edge reaches the height of 1.4 inch.



Figure 2. TT45 Joint



Figure 3. TT34 Joint



Figure 4. TT23 Joint



Figure 5. TT12 Joint

East Side



Figure 6. TT12 Joint



Figure 7. TT23 Joint




Figure 8. TT34 Joint



Figure 9. TT45 Joint



Figure 10. TT56 Joint