

Reflective Cracking Daily Testing Notes

Date: February, 2013

Project: Reflective Cracking Indoor Phase 2

Temperature: N/A

Reflective Cracking Testing Notes:

The full-scale test started on January 24, 2013. No mechanical issues were found on the rig. In addition, the asphalt-concrete interface temperature was constantly under 30°F. By the end of February, multiple cracks were through instrumentation, Figure 1.



Figure 1. Multiple Cracks detected through Instrumentation.

Reflective Cracking Instrumentation Status:

RC-Sensor activities were monitored during this period to ensure proper responses.