

## Reflective Cracking Testing Notes

**Date:** February 26, 2015

**Project:** Reflective Cracking Indoor Phase IV

**Weather:**

	6:54 AM	3:54 PM
Temperature (°F):	28.9	32.0
Dew Point (°F):	26.1	14.0
Humidity (%):	89	48
Visibility (Miles):	0.8	10.0
Wind (MPH):	10.4 NNE	9.2 N
Conditions:	Light Snow	Overcast

**Working Hours:** 7:00 AM – 4:30 PM

**Sub-Contractor(s):** None

**Personnel:** SRA

**Equipment:** Hand tools

**Reflective Cracking Testing Notes:**

An SRA engineer replaced the pressure differential switch on the chiller in an effort to troubleshoot the low flow fault and restore chiller operation.