

Reflective Cracking Testing Notes

Date: April 2, 2015

Project: Reflective Cracking Indoor Phase IV

Weather:

	6:54 AM	3:54 PM
Temperature (°F):	32.0	60.1
Dew Point (°F):	28.9	27.0
Humidity (%):	88	28
Visibility (Miles):	7.0	10.0
Wind (MPH):	Calm	15.0 SSW
Conditions:	Clear	Clear

Working Hours: 7:00 AM – 4:30 PM

Sub-Contractor(s): None

Personnel: SRA

Equipment: (1) pickup truck, (1) core drill with 4” I.D. core bit

Reflective Cracking Testing Notes:

The 18 mil test cycle continued on the South section of the test item.

An SRA technician continued obtaining asphalt cores from the test item for material characterization purposes. (10) additional cores 4 inches in diameter and approximately 7 inches thick were drilled and extracted from the East end of the P-401 test section atop the sampling slab to the West of the test rig. The cores were left adjacent to the reflective cracking test area after extraction.